



ENTRANCE NOTES:

1. IT IS IMPORTANT THAT THE CONTRACTOR SHOULD LOCATE THE ENTRANCE TO THE CAGE WITH THE MINIMUM DISTANCES SHOWN ON THE SHEET
2. PLAN TO SET THE POLE SO THAT THE ENTRANCE TO THE CAGE WILL BE LOCATED BETWEEN ANY TWO OF THE THREE STANCHIONS. LOCATE THE GATE IN THE MOST PRACTICAL POSITION FOR QUICK ACCESS.
3. THE FLOOR MUST BE LEVEL.
4. FOR INSTALLATION INSTRUCTIONS, SEE DETAILED INFORMATION ON SHEET B-1.

EBC	88004	McIntire Brass Works, Inc.
REV		MANUFACTURER'S DRAWING
NO.		AUTOMATIC SLIDING POLE
MODEL		MODEL 20
INSTALLATION DRAWING	B-2	
D	REV	Webb
DATE		1/1/69
SCALE		FULL
SHEET		1